









Architectural Concrete Repair Images

Explanatory Notes

The images illustrated here are some examples of Architectural concrete repair that clearly demonstrate the beneficial impact that repairs can have on the overall aesthetic qualities of fair faced concrete. These images have been selected so as to cover varied categories of repairs that GreyMatter concrete habitually encounter.

In order of appearance the repair categories are as follows:

- Tie hole repair (board marked finish GGBS concrete)
- Day joint/expansion joint repair to exterior smooth fair faced finish
- 'Holistic' repair to unsuitable 'bagging up' of extensive blowholes
- Arris edge repair to under compacted board marked finished concrete
- Extensive honeycombing to insufficient compacting of concrete with possible grout loss
- Remedial work to a previously repaired honeycombed concrete.
- Construction damage (board marked GGBS concrete)

In the majority of cases the requirement for Architectural repairs is not due to poor workmanship but rather through a lack of predicting how the material may behave. Through thorough planning, having the ability to foresee such issues and being in a position to utilise high quality Architectural repair methods, defects such as those seen here cease to be problems and begin to become challenges to resolve.